

JOULE TECHNOLOGIES, INC
4167 WEST ORLEANS STREET
MCHENRY IL 60050

PHONE: 815.759.0600
FAX: 815.759.6902
EMAIL: INFO@JOULETECHNOLOGIES.COM

This document was generated to serve as a checklist for the Test Engineer to create a complete package that articulates the requirements of a test program and fixture. If there are any questions on the requirements, please do not hesitate to call. Thank you.

Quote Requirements

1. Program and Fixture Statement of Work
2. ATE system configuration
3. Schematics
 - soft or hard copy
4. Assembly Drawings
 - soft or hard copy
5. Bill of Materials
 - soft copy including reference designators, part numbers, values, and tolerances
6. CAD data
 - Net List xy's and corresponding test points

Job Requirements

1. Hard copy PO
2. Two loaded gold boards
3. One bare board
4. Board Gerber files
5. GenRad or Teradyne
 - Drill file
6. Agilent
 - Component vias and pins' xy coordinates
 - Tooling holes' xy coordinates & diameter(s)

Note: Additional data may be required for boundary scan testing or other non-standard test requirements.